

Inspection Photos

Loc#413754

Operator: Sandridge

Inspection Number: 692400965

Inspection Date: 5/8/19





Photo#1:
Cellar grates (covers) of XX wells are not adjusted properly

May 7, 2019



Photo#2:
Cellar grates (covers) of XX wells, are not adjusted properly



Photo#3:
Senesced / dead, annual weeds are evident on location berms;

May 7, 2019



Photo#4:
Canada thistle rosettes were seen emerging on outside of West Berm.