

Inspection Photos
Location Name: CORNISH-66N63W /17NWNW
Location #: 306192



Photo #3
Cornish 17-11 Wellsite
Stained soil
from prior insp.



Photo #4
Cornish 17-11 Wellsite
Stained soil – appears remediated

Inspection Photos
Location Name: CORNISH-66N63W /17NWNW
Location #: 306192



Photo #5
Cornish 17-11 Condensate tank
Stained soil at loadout
from prior insp.



Photo #6
Cornish 17-11 Condensate tank
Stained soil at loadout – appears remediated

Inspection Photos
Location Name: CORNISH-66N63W /17NWNW
Location #: 306192



Photo #7
Cornish 17-11 Separator
Stained soil
from prior insp.



Photo #8
Cornish 17-11 Separator
Stained soil – appears remediated