

County: Boulder

Township: 2N **Range:** 69W **Section:** 21 **QQ:** NWNW

Original Latitude/ Longitude: 40.128896 / -105.1286

Updated Latitude/ Longitude: /

Basis for Location Change:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 580941 | Date: 7/17/1987 |
| | Doc #: 500207228 | Date: 5/12/1993 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 10/2/1991, Passed PA inspection 5/12/1993

Pit Status Review Summary:

Based on records review, there is no evidence that there was a pit on location. Inspection reports document a concrete water vault on location. Well was plugged and passed final reclamation inspection 5/12/1993. Pit status changed to closed.