

Inspection Photos

ALs Loc#439603

Operator: Sandridge

Inspection Number: 692400963

Inspection Date: 5/7/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:


Overview of Location to Northeast. Jeep and orange fence indicate Location of cellars with Conductors Set.

May 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge ALs Gregory Loc#439603



Photo#2:
From COGCC Maps; showing Well positions.

May 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge ALs Gregory Loc#439603