

Inspection Photos
Location Name: Cuykendall #12
Location ID: 318072



Pic 1



Pic 2 trash in motor house

Inspection Photos
Location Name: Cuykendall #12
Location ID: 318072



Pic 3 stained soil in motor house/trash



Pic 4 weeds around tanks, no capacity sign, thief hatch appears to be open.

Inspection Photos
Location Name: Cuykendall #12
Location ID: 318072



Pic 5 weeds/trash



Pic 6 weeds/trash

Inspection Photos
Location Name: Cuykendall #12
Location ID: 318072



Pic 7 stained soil possible leak in separator house



Pic 8 stained soil by combustor

Inspection Photos
Location Name: Cuykendall #12
Location ID: 318072



Pic 9 trash



Pic 10 weeds stained soil by wellhead