

Inspection Photos

Operator: Logos Operating
Location/API #: 063-05363
Date: 5-9-2019



Photo 1. View of the western project area from the northwestern corner facing southwestward.



Photo 2. View of erosional channeling within the northwestern project area.