

Inspection Photos

API: 05-073-06474

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing south along the former access road. There is predominately weeds (Kochia) growing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 2. Facing west along the former access road. There is predominately weeds (Kochia) growing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 3. Facing west toward the location. There is predominately weeds (Kochia) growing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 4. View of undesirable weed growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 5. Facing east toward the location. There is predominately weeds (Kochia) growing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 6. Facing south at the east side of the location. Vegetation is not establishing in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019

Inspection Photos



Photo 7. Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06474 | Date: 5/15/2019