

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2019

Submitted Date:

05/17/2019

Document Number:

689802648**FIELD INSPECTION FORM**Loc ID 313153 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone        | Email                  | Comment                         |
|-----------------|--------------|------------------------|---------------------------------|
| Maneotis, Karen | 970-620-6099 | Karen_Maneotis@swn.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 264315      | WELL | TA     | 01/24/2017  | GW         | 081-07096 | WALKER 3-2    | TA          |

**General Comment:**[COGCC Inspection 689802648 Report Summary](#)

On Wednesday 05/15/2019 at approximately 9:17, I, Inspector Emily Waldron, conducted a MIT witness at SWN Production Company Walker 3-2, at 05-081-07096 in Moffat County, Colorado.

While there, I observed a MIT. The MIT held 370 psi for 15 minutes. Test was passed in the field.

This is a summary of inspection 689802648 report.

**Inspected Facilities**Facility ID: 264315 Type: WELL API Number: 081-07096 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Inspector on location to witness MIT Form 42 401948907. Casing pressured to 370 PSI and held for 15 minutes. Test passed in the field.Corrective Action:  Date: \_\_\_\_\_**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 689802676    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826258">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826258</a> |