

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2019

Submitted Date:

05/17/2019

Document Number:

689802649**FIELD INSPECTION FORM**Loc ID 313134 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Maneotis, Karen	970-620-6099	Karen_Maneotis@swn.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259578	WELL	TA	07/27/2017	GW	081-07050	WALKER 3-1	TA

General Comment:[COGCC Inspection 689802649 Report Summary](#)

On Wednesday 05/15/2019 at approximately 9:48, I, Inspector Emily Waldron, conducted a MIT witness at SWN Production Company Walker 3-1, at 05-081-07050 in Moffat County, Colorado.

While there, I observed a MIT. The MIT held 370 psi for 15 minutes. Test was passed in the field.

This is a summary of inspection 689802649 report.

Inspected FacilitiesFacility ID: 259578 Type: WELL API Number: 081-07050 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Inspector on location to witness MIT Form 42 document number 401948903. Casing was pressured to 370 PSI and held for 15 minutes. Test was passed in the field.Corrective Action: Date: _____**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802677	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826259