

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/17/2019

Document Number:

689802655

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
313152 _____ Waldron, Emily _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10396
Name of Operator: SWN PRODUCTION COMPANY LLC
Address: PO BOX 12359
City: SPRING State: TX Zip: 77391

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Maneotis, Karen	970-620-6099	Karen_Maneotis@swn.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264314	WELL	TA	10/15/2009	GW	081-07095	WALKER 3-5	TA

General Comment:

[COGCC Inspection 689802655 Report Summary](#)
On Wednesday 05/15/2019 at approximately 12:00, I, Inspector Emily Waldron, conducted a MIT witness at SWN Production Company Walker 3-5, at 05-081-07095 in Moffat County, Colorado.
While there, I observed a MIT. The MIT held 400 psi for 15 minutes. Test was passed in the field.
This is a summary of inspection 689802655 report.

Inspected Facilities

Facility ID: 264314 Type: WELL API Number: 081-07095 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Inspector on location to witness MIT Form 42 document number 401948914. Casing was pressured to 400 PSI and held for 15 minutes. Test was passed in the field.

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802682	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826264