

Inspection Photos

API: 05-061-06797

Operator: BERRY ENERGY INC

Inspection Date: 5/15/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing south toward the location. Vegetation has not established and there are predominately weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019

Inspection Photos



Photo 2. View of weeds found throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019

Inspection Photos



Photo 3. Facing east at the location. Vegetation is bare in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019

Inspection Photos



Photo 4. Further to the west, vegetation is bare in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019

Inspection Photos



Photo 5. Facing north, across the road. Vegetation is bare in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019

Inspection Photos



Photo 6. Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06797 | Date: 5/15/2019