

Inspection Photos
Location Name: Walker 12-5
API: 05-081-07082

FORM 21
Rev. 9-14

Click here to reset the form

State of Colorado
Oil and Gas Conservation Commission

2240 Lincoln Street, Suite 800, Denver, Colorado 80202 (303) 894-2100 Fax: (303) 894-2109

MECHANICAL INTEGRITY TEST

1. The original pressure test must be conducted by a minimum of 2 operators.
2. The original pressure test must be conducted by a minimum of 2 operators.
3. The original pressure test must be conducted by a minimum of 2 operators.
4. The original pressure test must be conducted by a minimum of 2 operators.
5. The original pressure test must be conducted by a minimum of 2 operators.

Operator Number: 10266
Name of Operator: SWAN Production Company, LLC
Address: 10000 Energy Drive
City: Spring
State: TX
Zip: 77389
API Number: 05-081-07082
Well/Field Name: WALKER
Location Code: CML Section: 12 Township: 7N Range: 8E Meridian: 6E
Test Type: ☒ SHUT-IN PRODUCTION WELL ☐ INJECTION WELL
Test to Maintain SUT/TA status: ☐ Verification of Repairs: ☐ 5-year LIC ☐ Annual LIC Test
Describe Repairs or Other Work Activities:

Compliance the Attachment Checklist

Pressure Chart: ☐ Open: ☐ Closed: ☐
Casing Seal Test: ☐ Tubing Seal Test: ☐
Tubing Seal Test: ☐ Tubing Seal Test: ☐
Tubing Seal Test: ☐ Tubing Seal Test: ☐

Wellbore Data at Time of Test

Test Date: 5/16/19
Casing Pressure: 380 psi
Tubing Pressure: 380 psi
Test Witnessed by State Representative: ☐ Yes ☐ No

OSCC Field Representative (Print Name): Emily Waldron

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Russ Snowden
Signature: Russ Snowden
Title: Field Inspector
Date: 5-16-19

OSCC Approval: [Signature]
Comments of Approval, if any: [Signature]
Inspection Document #689802665

05 19 08 28

Photo 1. Photo of test Form 21 as filled out and signed in the field.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 689802665