

Inspection Photos
Location Name: Bull 11-8
API: 05-081-07269

Form 21
State of Colorado
Oil and Gas Conservation Division
Mechanical Integrity

Operator: SWN Production Company, LLC
Address: 11000 Energy Drive, Suite 100, Denver, CO 80231
City: Spring, State: TX, Zip: 77589
API Number: 05-081-07269, OGC Facility ID Number: 28087
Well Name: BULL, Well Number: 11-8
Casing Depth: 1845', Completion Date: 12/13/2014

Test Type:
☒ SHUT-IN PRODUCTION WELL
☐ INJECTION WELL
☐ Test to Maintain SITA status
☐ Verification of Repairs
☐ 5-year UIC
☐ Annual UIC Test
☐ Annual Packer

Wellbore Data at Time of Test:
Isolation/Production Zone(s): Perforated Interval: Open Hole Interval: Bridge Plug or Cement Plug Depth: 1845'

Tubing Casing/Annulus Test:
Tubing Size: Tubing Depth: Top Packer Depth: Multiple Packers? ☐ Yes ☒ No

Test Data:
Well State Survey Test: Casing Pressure: 5.0 psi, Casing Pressure - 10 Min: 0 psi, Casing Pressure - 30 Min: 360 psi, Casing Pressure - 60 Min: 360 psi, Pressure Loss or Gain During Test: 0 psi
OGC Field Representative (Print Name): Emily W. G. G. G.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.
Print Name: Russ Swank, Title: Field Inspector, Date: 5/16/19
Signature: [Signature], Title: Field Inspector, Date: 5/16/19
OGC Approval: [Signature], Title: Field Inspector, Date: 5/16/19
Inspection Document # 689802671

Photo 1. Photo of test Form 21 as filled out and signed in the field.