

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2019

Submitted Date:

05/17/2019

Document Number:

689802669

**FIELD INSPECTION FORM**

Loc ID 313285 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10396  
Name of Operator: SWN PRODUCTION COMPANY LLC  
Address: PO BOX 12359  
City: SPRING State: TX Zip: 77391

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                  | Comment                         |
|-----------------|--------------|------------------------|---------------------------------|
| Maneotis, Karen | 970-620-6099 | Karen_Maneotis@swn.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 284539      | WELL | TA     | 08/05/2013  | GW         | 081-07299 | GULCH 24-21   | TA          |

**General Comment:**

[COGCC Inspection 689802669 Report Summary](#)  
On Wednesday 05/16/2019 at approximately 10:10, I, Inspector Emily Waldron, conducted a MIT witness at SWN Production Company Gulch 24-21, at 05-081-07299 in Moffat County, Colorado.  
While there, I observed a MIT. The MIT held 360 psi for 15 minutes. Test was passed in the field.  
This is a summary of inspection 689802669 report.

**Inspected Facilities**

Facility ID: 284539 Type: WELL API Number: 081-07299 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Inspector on location to witness MIT Form 42 document number 401948859. Casing was pressured to 360 PSI and held for 15 minutes. Test was passed in the field.

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 689802697    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826551</a> |