

Inspection Photos
Location Name: McIntyre Pits #3 and #4
Facility ID: 421066



Pit Facility ID #418791. Ensure that 2' of freeboard exists in both pits, at all times.



Pit Facility ID #418790 gauge stick reads almost 12'.

Inspection Photos
Location Name: McIntyre Pits #3 and #4
Facility ID: 421066



Water transfer pipe joints and production equipment from nearby well pad remain on site.



Duck observed in lower pit.

Inspection Photos
Location Name: McIntyre Pits #3 and #4
Facility ID: 421066



Lower pit is at or near capacity. Ensure 2' of freeboard in both pits at all times.




Gauge stick in lower pit reads almost 12' also.

Inspection Photos
Location Name: McIntyre Pits #3 and #4
Facility ID: 421066



SG personnel pulled back the netting in the SW corner to allow an escape for the duck.



3' by 6' hole in netting on lower pit.