

Inspection Photos

Location Name: Brown HI Location ID 319554, Spill ID #448851, Remediation #10107

Inspection Date: 5/15/2019



Photo 1 – Abandoned dumlins recovered from excavation at former Brown HI Tank Battery.



Photo 2 – Photo viewing excavation near former dumlins, screening sample collected at 8' depth.

