

Pit Status Evaluation Form

Pit Overview:

Pit Name: BEISEL 1	Facility ID: 114327
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: J M RESOURCES INC / 44155	
Updated Operator: STARLIGHT RESOURCES LLC / 81825	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: API # 05-013-07108 (Facility ID 201704), Location ID 319877	

County: Adams			
Township: 1S	Range: 68W	Section: 1	QQ: NWNE
Original Latitude/ Longitude: 39.998678 / -104.952194			
Updated Latitude/ Longitude: 39.997662 / -104.949633			
Basis for Location Change:			
Well location updated based on aerial imagery			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698467 | Date: 2/16/1989 |
| | Doc #: 313421 | Date: 10/2/1996 |
| | Doc #: 1084233 | Date: 8/22/2001 |
| <input checked="" type="checkbox"/> | Form 27 Remediation Workplan – Project #: 696 | Date: 6/28/2001 |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314547 | Date: 2/11/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 112621, 114325 | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 7/5/2001

Timing of Pit Closure:

Closed with Remediation Project #696, 7/5/2001

Pit Status Review Summary:

Pit inventory report documents a 100BBL earthen water disposal pit. Pit was closed and replaced with a tank 7/5/2001, see remediation project #696.