

Inspection photos
SG 21-27
Api. # 05-045-07336



Location photo.



Separator units.

Inspection photos
SG 21-27
Api. # 05-045-07336



Chemical container.



Secondary containment is full.

Inspection photos
SG 21-27
Api. # 05-045-07336



Tank volumes are faded.



Tank volumes are faded.

Inspection photos
SG 21-27
Api. # 05-045-07336



Tank volumes are faded.



Tank volumes are faded.