

**Inspection Photos**  
**Location Name: KEHN USX AC-67N63W /35SWSW**  
**Location #: 310264**



**Photo #1**  
**Kehn USX AC 35-13 (05-123-26152) Wellsite**



**Photo #2**  
**Kehn USX AC 35-13 Battery**  
***Rain Puddles***

## Inspection Photos

Location Name: KEHN USX AC-67N63W /35SWSW

Location #: 310264



**Photo #3**  
**Kehn USX AC 35-13** Wellsite  
**Stain soil**  
*from prior insp.*



**Photo #4**  
**Kehn USX AC 35-13** Wellsite  
**Stain soil**  
**Remediation progressing**  
*muddy*

## Inspection Photos

Location Name: KEHN USX AC-67N63W /35SWSW

Location #: 310264



**Photo #5**  
**Kehn USX AC 35-13 Battery**  
**Stain soil**  
*from prior insp.*



**Photo #6**  
**Kehn USX AC 35-13 Battery**  
**Stain soil**  
*Appears remediated*  
*muddy*