

Inspection Photos
Location Name: Great Western 26-32
Location ID: 333062



Photo 1: Wellhead; unused equipment, missing emergency contact #.

