

Inspection Photos
Location Name: Great Western 26-42
Location ID: 333062



Photo 1: Wellhead; unused equipment, missing emergency contact #.



Photo 2: Centralized Tank Battery

Inspection Photos
Location Name: Great Western 26-42
Location ID: 333062



Photo 3: No placarding on produced water tank.