

**County:** Adams

**Township:** 1S      **Range:** 68W      **Section:** 2      **QQ:** NESE

**Original Latitude/ Longitude:** 39.991738 / -104.961714

**Updated Latitude/ Longitude:** /

**Basis for Location Change:**

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                 | Date:            |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664613         | Date: 9/22/1989  |
|                                     | Doc #: 500132136                            | Date: 12/27/1995 |
|                                     | Doc #:                                      | Date:            |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

Well PA 8/25/1995; passed final inspection 12/27/1995

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a concrete water vault on location. Well was plugged and passed final reclamation inspection 12/27/1995. Pit status has been changed to Closed.