

# Inspection Photos

API: 05-041-06067

Operator: ULTRA RESOURCES INC

Inspection and Photo Date: 5/14/2018



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-041-06067 | Date: 5/14/2019

## Inspection Photos



**Photo 1.** Facing west towards the access road. The vegetation has reestablished.



## Inspection Photos



**Photo 2.** The perimeter fence still remains around the location.



## Inspection Photos



**Photo 3.** Facing toward the location. The vegetation has reestablished.



## Inspection Photos



**Photo 4.** The degraded wattles remain at the location.



## Inspection Photos



**Photo 5.** Facing west toward the access road. Vegetation has reestablished.

