

Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|-----------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 698522 | Date: 11/9/1976 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 698528 | Date: 4/2/1985 |
| Doc #: 698526 | Date: 2/17/1989 |
| Doc #: 327563 | Date: 8/8/1995 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 2/23/1995, passed final inspection 8/8/1995.

Pit Status Review Summary:

Based on records review pit was replaced with a concrete water vault by 1985 inspections. Well was plugged and passed final reclamation inspection 8/8/1995. Pit status has been changed to Closed.