

Inspection Photos
Location Name: Federal 2-25
API: 05-081-06681



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Evidence of sediment and water migration on access road.