

# Inspection Photos

5/20/2019

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Inspection Doc. Number: 696200082

Washington County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 1:** Photo taken from the well head, facing west. Photo shows stained soils have not been removed from the wellhead.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 2:** Photo taken from the well head. Photo shows stained soils have not been removed from the wellhead.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 3:** Photo taken from the well head, facing south. Photo shows stained soils have not been removed from the wellhead.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 4:** Photos 4-8 were taken from the adjacent and interim areas of the well. Photos show equipment not needed for production remain stored on the location and interim areas.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 5:** See comments under photo 4

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 6:** See comments under photo 4

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 7:** See comments under photo 4

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 8:** See comments under photo 4

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 9:** Photo taken from the southeast corner of the well location. Previous inspections required operator to comply with rule 1003 and mark anchors. Photo shows anchor on the southeast end of the location has not been marked in accordance with 1003.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 10:** See comment under photo 9.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 11:** Photo taken from the south end of the pit. Photo shows Canada Thistle establishing on the location.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 12:** Photo taken from the south end of the pit. Photo shows Canada Thistle establishing on the location.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 13:** Photo taken from the south end of the pit. Photo shows Canada Thistle establishing on the location.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 14:** Photo taken from the pit. Photo shows Canada Thistle establishing on the location.

Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 15:** Photo taken from the pit. Photo shows Canada Thistle establishing on the location.