

Pls, Put on Computer



00599387

WELL SITE INSPECTION FORM



LOCATION NWNE 2-35-42W
OPERATOR VEGA ENERGY
WELL NAME #1-2 WITCHER

FIELD W/C - GREENWOOD
COUNTY BACA
PERMIT # 85-

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____ DEPTH: _____
BOP'S _____ RETURNS: _____ WOC: _____
CONTACT _____ CMT VOL: _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: YES _____ NO _____ PRODUCTION STRING: _____
WATER DISPOSAL: PITS _____, INJECTED _____, COMMERCIAL _____, UNKNOWN _____, N.A. _____
PITS: PERMIT Y _____ N _____, SKIM TANK Y _____ N _____, DIMENSIONS _____
LEASE SIGN: YES _____ NO _____ TANK ID: YES _____ NO _____ NA _____ FENCED: YES _____ NO _____
SURFACE EQUIPMENT: _____
COMMENTS: _____

DATE OF P&A INSPECTION 12/3/06

PITS BACKFILLED: YES ☒ NO _____ SURFACE RECLAIMED: YES ☒ NO _____
HOLE MARKER: YES ☒ NO _____ SITE CLEAN: YES ☒ NO _____
BOND RELEASE OK: YES ☒ NO _____ LANDOWNER RELEASE: YES _____ NO _____
COMMENTS: Site is Contoured Pasture - Sage & Yucca - Rig must
have had mud TKS - NO PITS - FENCE REPAIRED LOCATION SMOOTHED
* POSSIBLY PVC DRY HOLE MARKER

DATE OF SAFETY INSPECTION _____

COMMENTS: _____

INSPECTOR R. VACLAVIK

Jim

BEST IMAGE
AVAILABLE

API No. 05-009-6443

P&A Inspected: Yes ☒ No _____