

# Final Reclamation Inspection

May 20, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC-  
#10633

Location ID: 410164

Inspection Document #: 697500149

Weld County, CO

SENE Section 28 T3N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: FREDRIKSEN-63N68W  
Location ID: 410164



**Photo 1.** Photo taken from the approximate center of the facility/well location, facing West. Appears the Operator has performed final reclamation activities with the evidence of desirable vegetation; however, Operator has not performed final reclamation activities after removing the remaining equipment- see Photos - and there are areas with bare ground with no germination.



**Photo 2.** Photo taken from the approximate center of the facility/well location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: FREDRIKSEN-63N68W  
Location ID: 410164



**Photo 3.** Photo taken from the approximate center of the facility/well location, facing East. See comments under Photo 1.



**Photo 4.** Photo taken from the approximate center of the facility/well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: FREDRIKSEN-63N68W  
Location ID: 410164



**Photo 5.** Photo taken from the eastern facility/well location, facing Southeast.  
Photo illustrates an area with little, to no, germination.



Inspection Photos  
Location Name: FREDRIKSEN-63N68W  
Location ID: 410164



**Photo 6.** Photo taken from the southwestern facility/well location, facing South. Photo illustrates an area where equipment previously remained; however, Operator has failed to perform final reclamation activities throughout the areas where the equipment was removed.

Inspection Photos  
Location Name: FREDRIKSEN-63N68W  
Location ID: 410164



**Photo 7.** Photo taken from the southwestern facility/well location, facing East. See comments under Photo 6.