

Inspection Photos
Location Name: NCLP PC AA /08-19
Location #: 420423



Photo #1

Battery site

New Cache 8-24

NCLP PC AA 08-02D, 03D, 07D, 08D, 18D, 19

Abandoned – Equipment removed

Unused Gas meter run



Photo #2

NCLP PC AA 08-02D (05-123-32575) Wellsite

Temporarily Abandoned | TA



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: NCLP PC AA /08-19
Location #: 420423



Photo #3

NCLP PC AA 08-03D (05-123-32571) Wellsite
Temporarily Abandoned | TA



Photo #4

NCLP PC AA 08-18D (05-123-32573) Wellsite
Temporarily Abandoned | TA

Inspection Photos
Location Name: NCLP PC AA /08-19
Location #: 420423



Photo #5

NCLP PC AA 08-19 (05-123-32568) Wellsite

Temporarily Abandoned | TA