

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2019

Submitted Date:

05/21/2019

Document Number:

696100922

FIELD INSPECTION FORM

Loc ID 332986 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301052	WELL	AL	09/20/2010	LO	123-29896	NEW CACHE LA POU DRE 8-14(DIR)	AL
301053	WELL	AL	09/20/2010	LO	123-29897	NEW CACHE LA POU DRE 8-13(DIR)	AL

General Comment:

This is an **ABANDONED LOCATION** inspection.
Inspection purpose is to clear from snapshot map list.
Well status for 2 wellsites: **ABANDONED LOCATION (AL)**.

Inspected Facilities

Facility ID: 301052 Type: WELL API Number: 123-29896 Status: AL Insp. Status: AL

Facility ID: 301053 Type: WELL API Number: 123-29897 Status: AL Insp. Status: AL

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built Pass

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation Pass

Well Release on Active Location

Multi-Well Location

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE MAY 21, 2019 at approximately 12:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: NCLP PC AA /08-07D Location ID: 332986 Location County: Weld County, Colorado Weather: Rain w/ mud & puddles. While there, I observed: 2: Wellsites: ABANDONED LOCATION (AL). NO sign of oil & gas activity observed. Routine inspection. Inspection purpose is to clear from snapshot map list.</p> <p>NO: Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>05/21/2019</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100923	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4829189