



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	May 7, 2019 6:57:19 PM MDT
Server Receive Date:	May 16, 2019 1:16:39 PM MDT
Reference Number:	20190508-18105653291
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	May 7, 2019
Well Name	LEMON GAS UNIT J 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Repaired Berm Grading of Well Pad Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

