

Form Information

---

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 20, 2019 7:45:45 AM MDT
Server Receive Date:	May 20, 2019 7:46:03 AM MDT
Reference Number:	20190520-18106879446
Location:	Unknown Location

Information

---

Name	colen@horizonenvservices.com
Date	May 13, 2019
Well Name	DAUGHETEE, LA GAS UNIT 2
API Number	50670885200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



### Picture West to East



### Additional photos



### Completed work description

Sprayed thistle populations in the interim reclamation area, fixed erosion channels and installed small rock checks to slow the runoff from pad. Removed weed debris from location.