



00275409

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)Well Name GLASSBURN #2API Number 05 -075 - 9227Operator NENW23-10N-52WPermit # 90-1288Location DOHENYCounty LOGANField BRULEInspector R. Van Sickle

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) ☒ Fail(N) ☐ Date 7-10-91 ND ☐ DG ☐ WO ☐ PR ☐ SI ☐ TA ☐

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____

Consistent with APD casing Program? YES ☐ NO ☐ Returns _____

Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____

Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: ☐ Sign: Yes ☐ No ☐Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLsEquipment _____ Meter Run: Yes ☐ No ☐Bradenhead Press: _____ Fluid: No ☐ Yes ☐ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 1

Date Permit Expired: _____

Hole Plugged: Yes ☒ No ☐Pits Backfilled: Yes ☒ No ☐Material Buried: Yes ☒ No ☐ N/A ☐Site Clean: Yes ☒ No ☐Bond Release OK: Yes ☒ No ☐ Fed ☐Hole Marker: Yes ☐ No ☒

Date of Safety/Status Inspection _____

Comments: _____

Violations: Yes ☐ No ☐ Notice Sent: Yes ☐ No ☐ Date Sent: _____