

Pit Status Evaluation Form

Pit Overview:

Pit Name: GINTHER	Facility ID: 114315
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: U S MINERAL & ROYALTY CORP / 90895	
Updated Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO INC / 27635	
Form 15 Pit Permit Doc #: 664472	Permit Date: 111/22/1976
Related Facilities: API # 05-001-06952 (Facility ID 201549), Location 319844; API # 05-001-06977 (Facility ID 201574); API # 05-001-06945 (Facility ID 201542)	

County: Adams			
Township: 1S	Range: 67W	Section: 20	QQ: SWNW
Original Latitude/ Longitude: NA		/ NA	
Updated Latitude/ Longitude: 39.952058		/ -104.9211	
Basis for Location Change: Pit location updated based on historical aerial imagery.			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes: 	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 664472 | Date: 11/22/1976 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 664455 | Date: 6/19/1990 |
| Doc #: 305641 | Date: 8/8/1995 |
| Doc #: 305640 | Date: 10/6/1997 |
| <input checked="" type="checkbox"/> Form 27 Remediation Workplan – Project #: 10065 | Date: 4/24/2017 |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input checked="" type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: 118914, 118915 | |
| <input type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 4/24/2017

Timing of Pit Closure:

Pit closure under remediation project #10065, resolved 4/24/2017

Pit Status Review Summary:

Duplicate of pits 118914 and 118915. Based historic inspections, a 10X20 pit existed on location; pit was replaced by a concrete water vault by 1997 inspections. Pit closure under remediation project #10065, resolved 4/24/2017. Pit status has been changed to Closed.