

Meagher 10-1H
API: 05-103-11854
Inspection: 679704177



Photo 1. Location looking southeast.

Meagher 10-1H
API: 05-103-11854
Inspection: 679704177



Photo 2. Assortment of trash stored mixed in with usable equipment. Barrels with no secondary containment.



Photo 3. Assortment of trash stored on edge of location mixed in with usable equipment.