

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> FREEMAN 1A	<b>Facility ID:</b> 113804
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> VESSELS OIL & GAS COMPANY / 93200	
<b>Updated Operator:</b> CUTLER BROTHERS - 22170	
<b>Form 15 Pit Permit Doc #:</b> NA	<b>Permit Date:</b> NA
<b>Related Facilities:</b> API # 05-001-07092 (Facility ID 201689), Location 375965	

<b>County:</b> Adams			
<b>Township:</b> 1S	<b>Range:</b> 66W	<b>Section:</b> 31	<b>QQ:</b> SWSE
<b>Original Latitude/ Longitude:</b> NA / NA			
<b>Updated Latitude/ Longitude:</b> 39.916458 / -104.815122			
<b>Basis for Location Change:</b>			
Corrected range (was 6W not 66W). Lat/long created based on historic aerial imagery.			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA              | Date: NA         |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 312437         | Date: 10/26/1996 |
|                                     | Doc #:                                      | Date:            |
|                                     | Doc #:                                      | Date:            |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 4/24/2017**

#### Timing of Pit Closure:

Well PA 1/19/1996, passed final inspection 10/26/1996.

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location. Well was plugged and passed reclamation inspection 10/26/1996. Pit status has been changed to Closed.