

Pit Status Evaluation Form

Pit Overview:

Pit Name: ZARLENGO	Facility ID: 114279
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: CORAL-CENTRAL OPERATING INC / 20263	
Updated Operator: KP KAUFFMAN COMPANY INC / 46290	
Form 15 Pit Permit Doc #: 698317	Permit Date: 12/5/1978
Related Facilities: API 001-07141 (Fac 201737), Loc 335715; API 001-06795 (Fac 201392); API 001-07486 (Fac 202081); API 001-08043 (Fac 202638); API 001-09014 (Fac 203455)	

County: Adams			
Township: 1S	Range: 67W	Section: 4	QQ: W2
Original Latitude/ Longitude: 39.993399 / -104.898622			
Updated Latitude/ Longitude: 39.994549 / -104.902758			
Basis for Location Change:			
Pit location updated based on historical aerial imagery.			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 698317 | Date: 12/5/1978 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698356 | Date: 2/16/1989 |
| | Doc #: 304989 | Date: 5/25/1998 |
| | Doc #: | Date: |
| <input checked="" type="checkbox"/> | Form 27 Remediation Workplan – Project #: 7388 | Date: 4/1/16 |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314547 | Date: 2/11/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 113812, 112659 | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed


Pit Status Date: 4/1/16

Timing of Pit Closure:

Remediation of pit area covered in remediation project number 7388, resolved 4/1/16

Pit Status Review Summary:

Duplicate of pits 113812 and 112659. Based on records review, a 100BBL earthen water disposal pit existed on location. Remediation of the former pit area was covered under remediation project #7388, resolved 4/1/2016. Pit status has been changed to Closed.



6/1993

N

Imagery U.S. Geological Survey

1993 Imagery
Google Earth

1993

Imagery Date: 6/26/1993 39°59'38.35" N 104°54'16.44" W elev 0 ft eye alt 923 ft