

**Inspection Photos**  
**Location Name: Lauridson #2A**  
**Location ID: 318088**



**Photo 1 WH and PU**



**Photo 2 WH sign**

**Inspection Photos**  
**Location Name: Lauridson #2A**  
**Location ID: 318088**



**Photo 3 Unused equipment: What appears to be a flow back tank disconnected form WH**