

Inspection Photos
Location Name: Lauridson #1-A
Location ID: 317934



Photo 1 WH



Photo 2 Production line not connected and bull plugged



Inspection Photos
Location Name: Lauridson #1-A
Location ID: 317934



Colorado Oil and Gas Conservation Commission
40.04867, -104.92595, 1548.5m
May 22, 2019 14:28:04

**Photo 3 Unused equipment: Walking beam and horses head
laying on location.**