

Inspection Photos
Location Name: Lindstrom 24-8-67 1H
Location ID: 425165



Photo 1: Location photo at entrance.



Photo 2: Pumpjack

Inspection Photos
Location Name: Lindstrom 24-8-67 1H
Location ID: 425165



Photo 3: Tank Battery



Photo 4: Tank Battery sign; MISSING EMERGENCY CONTACTS.



Inspection Photos
Location Name: Lindstorm 24-8-67 1H
Location ID: 425165



Photo 5: Stained soil behind middle crude oil tank.



Photo 6: Trash at head of pumpjack

Inspection Photos
Location Name: Lindstorm 24-8-67 1H
Location ID: 425165



Photo 7: Door off pumpjack motor.