

# Inspection Photos

API: 05-071-06671

Operator: Evergreen NATURAL RESOURCES

Inspection Date: 5/22/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-06671 | Date: 5/22/2019

## Inspection Photos



**Photo 1.** Facing along the access road where culvert was filled in at Lat/Long:37.09966,-104.73441. A new culvert has been installed and erosion corrected.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06671 | Date: 5/22/2019

## Inspection Photos



**Photo 2.** Rock rip/rap has been installed at the outlet.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06671 | Date: 5/22/2019

## Inspection Photos



**Photo 3.** Rock check dams have been installed along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06671 | Date: 5/22/2019

## Inspection Photos



**Photo 4.** A water bar has been installed and the road was graded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06671 | Date: 5/22/2019

## Inspection Photos



**Photo 5.** Facing east toward the TAD POLE #21-12 location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06671 | Date: 5/22/2019