

Inspection Photos

API: 05-071-06601

Operator: Evergreen NATURAL RESOURCES

Inspection Date: 5/22/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06601 | Date: 5/22/2019

Inspection Photos



Photo 1. New culverts and rock rip/rap were installed along the main road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06601 | Date: 5/22/2019

Inspection Photos



Photo 2. Facing toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06601 | Date: 5/22/2019

Inspection Photos



Photo 3. Vegetation is well established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06601 | Date: 5/22/2019