

## Inspection Photos

Location Name: Federal #1-3-8-104

Location ID: 322449

Inspection Date: May 15, 2019



**Photo #1 – (COGIS Maps) Aerial view of the Location (ID# 322449). The green square represent the pit location (ID# 119457) and the red dot represents a well (API# 05-045-06287).**



**Photo #2 – View of the pit looking east. Weeds can be seen growing in and around the pit. The disturbed area at the base of the pit is where the operator collected their soil sample.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Federal #1-3-8-104**  
**Location ID: 322449**  
**Inspection Date: May 15, 2019**



**Photo #3 – View of a unmarked flowline riser looking southwest.**



**Photo #4 – View of location looking north, site wide weeds.**

