

Inspection Photos
Location Name: Federal #21-4X
Location ID: 323898
Inspection Date: May 15, 2019



Photo #1 - (COGIS Maps) Aerial view of the Location (ID# 323898). The green square represent the pit location (ID# 119479) and the red dot represents a well (API# 05-045-06879).



Photo #2 – Location sign.



Inspection Photos
Location Name: Federal #21-4X
Location ID: 323898
Inspection Date: May 15, 2019



Photo #3 – View of the flow line riser.



Photo #4 – View of plastic produced water tank sign.



Inspection Photos
Location Name: Federal #21-4X
Location ID: 323898
Inspection Date: May 15, 2019



Photo #5 – View of pit looking north east.



Photo #6 – View of pit looking north west, site vegetation can be seen in the background.

