

Inspection Photos
Location Name: Federal #23-4
Location ID: 322413
Inspection Date: May 15, 2019



Photo #1 - (COGIS Maps) Aerial view of the Location (ID# 322413). The green square represent the pit location (ID# 119476) and the red dot represents a well (API# 05-045-06198).



Photo #2 – Location sign.



Inspection Photos
Location Name: Federal #23-4
Location ID: 322413
Inspection Date: May 15, 2019



Photo #3 – Plastic drum east of well head missing NFPA placard.



Photo #4 – Plastic drum north of separator.



Inspection Photos
Location Name: Federal #23-4
Location ID: 322413
Inspection Date: May 15, 2019



Photo #5 – Vegetation around horizontal heated separator.



Photo #6 – View of pit (119476) with the partly buried 95 bbl produced water tank to the south.



Inspection Photos
Location Name: Federal #23-4
Location ID: 322413
Inspection Date: May 15, 2019



Photo #7 – View of 95 bbl partly buried produced water tank looking north.



Photo #8 – View of 95 bbl partly buried produced water tank fluids.

