

## Inspection Photos

Location Name: Federal #31-16

Location ID: 322412

Inspection Date: May 15, 2019



Photo #1 - (COGIS Maps) Aerial view of the location (ID# 322412). The green square represent the pit location (ID# 119480) and the red dot represents a well (API# 05-045-06197).



Photo #2 – Location sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Federal #31-16**  
**Location ID: 322412**  
**Inspection Date: May 15, 2019**



**Photo #3 – Oil stained soil beneath the valve on the produced water tank. Pit 119480 located southwest of the produced water tank. Photo taken looking north**



**Photo #4 – View of site wide vegetation looking south**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources