

Inspection Photos
Location Name: Lind Farms 26-11
Location ID: 310231



Photo 1: (TA) Pumpjack



Photo 2: unused equipment



Inspection Photos
Location Name: Lind Farms 26-11
Location ID: 310231



Photo 3: Unused equipment.



**Photo 4: Bucket of unknown substance not in containment/
unused equipment**



Inspection Photos
Location Name: Lind Farms 26-11
Location ID: 310231



Photo 5: Tank Battery



Photo 6: Unused equipment

Inspection Photos
Location Name: Lind Farms 26-11
Location ID: 310231



Photo 7: Unused equipment



Photo 8: Bucket of unknown substance (trash)

