

Inspection Photos
Location Name: Casa Loma/ Hirsch Battery
Location ID: 430703



Photo 1: Centralized Tank Battery



Photo 2: NO SIGNAGE for produced water tank or placard

Inspection Photos
Location Name: Casa Loma/Hirsch Battery
Location ID: 430703



Colorado Oil and Gas Conservation Commission
40.55104, -104.85241, 1492.2m, 65°
May 23, 2019 10:53:59

Photo 3: Unused equipment



Colorado Oil and Gas Conservation Commission
40.55106, -104.85241, 1492.4m, 246°
May 23, 2019 10:54:15

Photo 4: Trash inside gas meter house

