

Inspection Photos
Location Name: Schlotthauer 14-23
Location ID: 426759



Photo 1: Wellhead



Photo 2: Centralized Tank Battery



Inspection Photos
Location Name: Schlotthauer 14-23
Location ID: 426759



Photo 3: No BBLs on produced water tank.



Photo 4: Not legible BBLs on produced water tank

Inspection Photos
Location Name: Schlotthauer 14-23
Location ID: 426759



Photo 5: (2) Unused risers



Photo 4: Not legible BBLS on produced water tank

