

Inspection Photos
Location Name: Ranchero/Lake Battery
Location ID: 429097



Photo 1: Centralized Tank Battery



Photo 2: No BBLs on South produced water tank.

Inspection Photos
Location Name: Ranchero/Lake Battery
Location ID: 429097



Photo 3: No BBLs on North produced water tank.



Photo 4: (2) Unused risers

Inspection Photos
Location Name: Ranchero/Lake Battery
Location ID: 429097



Photo 5: Erosion at entrance of loction.



Photo 6: More erosion at entrance.

Inspection Photos
Location Name: Ranchero/Lake Battery
Location ID: 429097



Photo 6: Trash/unused equipment inside east gas meter house/oily waste.